Monday, 05/01/2009 7:58:27 AM

User:

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number**

S.O. No. :

: 44372 : 11058

P.O. Number

This Issue : 05/01/2009

Prsht Rev. : NC

: //

: 43385

Type

: MACHINED PARTS

Part Number

Drawing Name

: D28921

Drawing Number

: D2892 REV A 1

: 02.500 BLUE

Project Number Drawing Revision

: N/A : A

Material

Due Date

: 31/01/2009

Qty:

6 Um: Each

Checked & Approved By

Comment

Written By

First Issue

Previous Run

Added P/O

Est. D 08.03.19

Re-format EC verified by: DD

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

DSK077

D2892-1 TURNING DETAIL



Comment: Qty.:

0.5000 Each(s)/Unit Total: 3.0000 Each(s)

D2892-1 TURNING DETAIL

43869 Batch:

09/01/07

2.0

HAAS1

HAAS CNC VERTICAL MACHINING #1



Comment: HAAS

Machine as per Folio FA082

Tumble & Deburr

INSPECT PARTS AS THEY COME OFF MACHINE

3.0

QC2



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



5.0



Comment: SECOND CHECK

SPRAY PAINTING



Comment: SPRAY PAINTING

--PRIME grey
-SPRAY PAINT DELFLEET BLUE B 10077 -CLEAR DELFLEET

B 110161

09-01-12

Dart Aerospace Ltd WORK ORDER CHANGES W/O: **Approval Approval** DATE **STEP** PROCEDURE CHANGE By Qty Chief Eng / **Date** QC Inspector Prod Mgr Part No: ______ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: ____ Date: _____ Date: WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B Approval **Description of NC** Verification Approval DATE STEP Sign & Initial Action Description

	 Section A	Chief Eng	Chief Eng	Date	Section C	Chief Eng	QC Inspector
					:		
L	 	1	I and the second	I	1	1	l

NOTE: Date & initial all entries

Date: Monday, 05/01/2009 7:58:27 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: 02.500 BLUE Job Number: 44372 Part Number: D28921 Job Number: Seq. #: **Machine Or Operation:** Description: 6.0 INSPECT SPRAY PAINT 0901 Comment: INSPECT SPRAY PAINT 7.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: X 8.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart	Aeros	pace	Ltd

W/O:		 WOR	WORK ORDER CHANGES						
DATE	STEP	PROCEDURÈ CHANG	E		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·							
				· · · · · · · · · · · · · · · · · · ·					
	ļ. ;			,					

Part No:	** **	PAR #:	Fault Category:*	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		\	WORK ORDE	ER NON-CONFORMANCI	E (NCR)				
		Description of NC		Corrective Action Section B		Verification	Approval	Approval	
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		Section C	Chief Eng	QC Inspector		
· · · · · · · · · · · · · · · · · · ·				i					
						1			

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	44372
Description: Ø2.500 Support	Part Number:	D2892-1
Inspection Dwg: D2892 Rev: A		Page 1 of 1

		FIRST	ARTICLE INS	SPECTION	DIMENSIO	ON SHEET	「	
			X First A	rticle [Protot	type		· .
					ensions			
Dim	Min	Max	Go/No Go Gauge	1	2	3	4	5
				HAAS Section	n			•
AA	0.115	0.135		- 13,2	.131	-132	./32	-/32
AB	0.290	0.310		-310	310	.310	-310	-310
AC	0.040	0.060		-049	, 050	.050	.051	120.
AD	0.115	0.135		- 124	123	- 123	-124	.124
AE	0.240	0.260		.252	-252	-250	-249	-250
AF	0.188	0.193		-189	189	189	189	.189
AG	0.240	0.260		-250	· 250	,250	-250	.250
AH	1.126	1.146	-	1.140	1.140	1.136	1.135	1./34
Al	0.454	0.474		· H68	467	.464	-465	464
AJ	0.240	0.260		.250	aso	-250	-250	-250
AK	0.053	0.073		. 063	-063	. 063	- 063	-063
AL	0.257	0.262		. 259	-259	,259	-259	-259
AM	1.663	1.683		1.675	1.645	1.675	1.675	1.675
AN	0.053	0.073		-063	- 063	-063	-063	- 063
AO	0.022	0.042		- 032	-032	-032	-032	-032
AP	2.779	2.789		2.784	2.784	2-784	2,784	2.784
AQ							, , , , , ,	
AR								
AS	1							
AT								
			Accept/Reject					
	Measure	d by:	J.L			Date:	09/01/0	7
	Audite	d by:	AZ			Date:	09/01	/ de
Proto	type Appr	oval:				Date:		
Rev	Date	Change				Pa	vised by	Approved
A	02.12.12	New Issue					/RF 1.0	Approved
<u>A</u>	08.04.21	Reformat			,		JLM A	7/
Ď	00.04.21	Reformat				KJ	APPIN AX	

DART AEROSPACE LTD	Work Order:	44310
Description: Ø2.500 Support	Part Number:	D2892-1
Inspection Dwg: D2892 Rev: A		Page 1 of 1

шэрс	Ction Dwg	. DZ00Z	1107.71				<u> </u>	ge i oi i
		FIRST	ARTICLE INS	SPECTION	DIMENSIC	ON SHEET		
			X First A	rticle [Protot	type		_
					Record	Actual Dime	nsions	
Dim	Min	Max	Go/No Go Gauge	16	×	13	Ą	5
	L		· •	HAAS Section	1			
AA	0.115	0.135		./32		· .		
AB	0.290	0.310		-310				
AC	0.040	0.060		.049				
AD	0.115	0.135		. 124				
AE	0.240	0.260		-249				
AF	0.188	0.193		.189				
AG	0.240	0.260		.250	_			
AH	1.126	1.146		1.136				
Al	0.454	0.474		-4/64				
AJ	0.240	0.260		.250				
AK	0.053	0.073		.063				
AL	0.257	0.262		.259				
AM	1.663	1.683		1.675				
AN	0.053	0.073		- 063				
AO	0.022	0.042		-033	, , , , , , , , , , , , , , , , , , , ,			
AP	2.779	2.789		-032 2-784				
AQ				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
AR								
AS								
AT								
			Accept/Reject					
	Measured	by:	J.L		_	Date:	09/01	107
			-			, <u> </u>	-0 1	- (2
	Audited	by:	17			Date:	07/0	21/10/2
Proto	type Appro	val:				Date:		
Rev	Date	Change	=			Rev	ised by	Approved
Α		New Issue				KJ/		21
В	08.04.21	Reformat				KJ/	JLM of	411

1.00 <u>;</u> -